

From: [Johnny Titsworth](#)
To: [Bratcher, Mike, EMNRD](#); [Patterson, Heather, EMNRD](#); [Tucker, Shelly](#)
Cc: [Kyle Adams](#); [Leslie Garvis](#)
Subject: Gissler B 31 work plan
Date: Thursday, March 17, 2016 1:06:07 PM
Attachments: Gissler B 31 work plan (2).pdf

Mike/Heather/Shelly

Attached is the work plan & analytical for the remediation of the Gissler B 31. We collected samples down to 20' below surface. We were not able to get and deeper samples due to a dense caliche barrier. We weren't able to completely delineate, but we did show that the chlorides did decrease at deeper levels. I believe that the chlorides are being held up at the barrier. We would like to proceed with the remediation, so that we can start the regrowth process before the growing season. If there are any questions or concerns, feel free to contact us. Thanks.

Johnny Titsworth
HSE COORDINATOR

BURNETT OIL CO., INC.
P.O. Box 188
CR 220 North
Loco Hills, NM 88255
MOBILE: (432)-425-2891
EMAIL: jitsworth@burnettoil.com

This message is intended only for the person(s) to which it is addressed and may contain privileged, confidential and/or insider information. If you have received this communication in error, please notify us immediately by replying to the message and deleting it from your computer. Any disclosure, copying, distribution, or the taking of any action concerning the contents of this message and any attachment(s) by anyone other than the named recipient(s) is strictly prohibited.