

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

nMLB1211546451

**OPERATOR**☐ Initial Report ☒ Final Report

<b>Name of Company:</b> Chesapeake Operating, Inc.	<b>Contact:</b> Bradley Blevins
<b>Address:</b> 1616 West Bender, Hobbs, NM 88240	<b>Telephone No.:</b> (575) 391-1462. ext. 86424
<b>Facility Name:</b> Brushy 12 Federal 1	<b>Facility Type:</b> Tank Battery

<b>Surface Owner:</b>	<b>Mineral Owner:</b>	<b>API No.:</b> 3001525416
-----------------------	-----------------------	----------------------------

**LOCATION OF RELEASE**


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	12	26S	29E	560	South	1980	West	Eddy

**Latitude:** N32° 03' 04.77"**Longitude:** W103° 56' 18.66"**NATURE OF RELEASE**

<b>Type of Release:</b> Oil	<b>Volume of Release:</b> 35-bbls	<b>Volume Recovered:</b> 5-bbls
<b>Source of Release:</b> Hot Oil Unit	<b>Date and Hour of Occurrence:</b> 3/27/12	<b>Date and Hour of Discovery:</b> 3/27/12 @ 16:00 hrs
<b>Was Immediate Notice Given?</b> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	<b>If YES, To Whom?</b> NMOCD; BLM	
<b>By Whom?</b> Bradley Blevins	<b>Date and Hour:</b> 3/27/12 @1600 hrs.	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse:</b> Not Applicable	
<b>If a Watercourse was Impacted, Describe Fully.*</b> Not Applicable		

**Depth to Groundwater:** ~ 125 feet**Describe Cause of Problem and Remedial Action Taken.\*** A hot oil unit caught fire releasing 35 bbls of oil with 5 bbls recovered. An Emergency Response Team arrived at the release area and began continuous abatement of the impacted area.**Describe Area Affected and Cleanup Action Taken.\*** Approximately 23,940 square feet of area was affected by the release of ± 35-bbls of oil. ± 5-bbls of oil were recovered from the site. Standing liquid was scraped up, blended and stock piled on location. Impacted material was placed on the contaminated caliche to prevent additional contamination of the area. Contaminated soil was hauled to a state approved disposal facility and site backfilled with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<b>Signature:</b> 		<b>OIL CONSERVATION DIVISION</b>	
<b>Printed Name:</b> Bradley Blevins		<b>Approved by District Supervisor:</b> MBratcher	
<b>Title:</b> EH & S Field Specialist		<b>Approval Date:</b> 3/24/16	<b>Expiration Date:</b> N/A
<b>E-mail Address:</b> bradley.blevins@chk.com		<b>Conditions of Approval:</b> FINAL	
<b>Date:</b> 6.22.12 <b>Phone:</b> (575) 391- 1462, #86424		<b>Attached</b> <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-1105