

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy Production	Contact Rudy Zuniga, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575-390-5435
Facility Name Sand 7 Fed 1	Facility Type Oil
Surface Owner Federal	Mineral Owner Federal
API No. 30-015-25901	

LOCATION OF RELEASE

Unit Letter K	Section 7	Township 18S	Range 31E	Feet from the 1980'	North/South Line FSL	Feet from the 2121'	East/West Line FWL	County Eddy
-------------------------	---------------------	------------------------	---------------------	-------------------------------	--------------------------------	-------------------------------	------------------------------	-----------------------

Latitude: 32.75989

Longitude: -103.90954

NATURE OF RELEASE

Type of Release Spill	Volume of Release 7bbls	Volume Recovered 2bbls
Source of Release hammer union on recirculation pump	Date and Hour of Occurrence December 3, 2014 10:30 AM	Date and Hour of Discovery December 3, 2014 10:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson, BLM & Mike Bratcher, OCD	
By Whom? Rudy Zuniga, Production Foreman	Date and Hour December 3, 2014 11:20 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

On December 3, 2014 at 10:30am Lease Operator was transferring oil with the recirculation pump at the Sand 7 Fed 1 when he discovered the hammer union leaking releasing 7bbls of oil in pasture. When Lease Operator discovered the leak he immediately shut down the recirculation pump and notified the Assistant Production Foreman.

Describe Area Affected and Cleanup Action Taken.*

The area affected is approximately 2'x10' in the pasture area North of the Sand 7 Fed 1. Franco's Trucking was contacted and were able to recover 2bbls of oil from the spill by vac truck.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher		
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: Sheila.Fisher@dvn.com	Approval Date:	Expiration Date:
Date: Phone: 575.748.1829	Conditions of Approval:	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary



7-185-31E
NESW

* Sand 7 Fed 1 7bbls Oil Spill

Devon GIS Mapping



Disclaimer: This plot is for illustrative purposes only and is neither a legally recorded map nor a survey and is not intended to be used as one.

Scale: 1:1,128

Date Printed: 12/4/2014 9:43:07 AM







