Hi Heather,

Here is a map of the last sampling event on this location. As promised, I have over laid the sample results from Cardinal. Once you have had a chance to review it, just let me know what it is that you think would work in terms of remediating this site. Actually, the pad area doesn't look to bad to me. Groundwater is 182' bgs. Let me know and I will revise the work plan to accommodate the NMOCD guidelines and re-submit. I do have BLM approval, so I just need to know how I can accommodate the OCD. I truly thank you for your help as I know that I am in the queue behind many others lol.

Thank You

Rebecca Pons

Safety & Environmental Solutions, Inc. 703 East Clinton Street Hobbs, NM 88240 Office: (575) 397-0510