

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Flying Squirrel Federal #1H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner:	API No. 30-015-42608
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter I	Section 30	Township 18S	Range 31E	Feet from the 2000'	North/South Line South	Feet from the 450'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.7167244 Longitude -103.9017334

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 20 bbls Oil ; 8 bbls PW	Volume Recovered: 3 bbls Oil ; 3 bbls PW
Source of Release: Gasket Failure	Date and Hour of Occurrence: 8/11/2015 6:30 pm	Date and Hour of Discovery: 8/11/2015 6:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: Thu 8/13/2015 5:56 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a gasket failure on FWKO. A vacuum truck was dispatched to recover all standing fluid. Crews with soapy water and Microblaze were also dispatched to treat the area.

Describe Area Affected and Cleanup Action Taken.*

This release caused a spray that impacted the nearby pasture. This release was completed with an approved work plan under the guidance of NMOCD and BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Amanda T. Davis

Printed Name: Amanda Trujillo Davis

Approved by Environmental Specialist:

Title: Senior Environmental Coordinator

Approval Date: 6/1/2016

Expiration Date: N/A

E-mail Address: atrujillo@concho.com

Conditions of Approval:

Attached ☐

Date: May 20, 2016 Phone: 575-748-6940

FINAL

* Attach Additional Sheets If Necessary

2RP-3234