

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 5/27/2016

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Dodd Federal Unit South Battery	Facility Type: Battery

Surface Owner: Federal	Mineral Owner:	API No.
------------------------	----------------	---------

LOCATION OF RELEASE

Unit Letter J	Section 22	Township 17S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.816895 Longitude -104.060867

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 50 bbls Oil	Volume Recovered: 0 bbls Oil
Source of Release: LACT	Date and Hour of Occurrence: 12/30/2015 11:00 am	Date and Hour of Discovery: 1/5/2015 12:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mr. Bratcher - NMOCD / Mr. Amos - BLM	
By Whom? Amanda Trujillo Davis	Date and Hour: Wed 1/6/2016 3:40 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused when a pipe on the LACT cracked due to the cold weather. It caused the oil in the production tank to empty into the containment. Due to the inclement weather and impassable roads the release was not discovered immediately. Hydro Vacs were dispatched to recover standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred primarily within the battery however some fluid breached the containment and ran along the road. COG completed the reclamation of this area under the guidance on NMOCD and BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amanda T. Davis</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 6/1/2016	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: May 27, 2016 Phone: 575-748-6940	FINAL	

* Attach Additional Sheets If Necessary

2RP-3492