State of New Mexico Energy Minerals and Natural Resources

Received 6/7/2016 NMOCD Artesia

> Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in

## District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV

Oil Conservation Division

accordance with 19.15.29 NMAC. 1220 South St. Francis Dr. 1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505 **Release Notification and Corrective Action OPERATOR** ☐ Initial Report Final Report Name of Company Contact Yates Petroleum Corporation Amber Griffin Address Telephone No. 104 S. 4th Street 575-748-1471 Facility Type Facility Name Aparejo APA Battery Battery Surface Owner Mineral Owner API No. State State 30-015-28327 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County 16 19S 25E 660 North 660 West Eddy Latitude 32.66637 Longitude 104.49569 NATURE OF RELEASE Type of Release Volume of Release Volume Recovered Crude Oil 18 B/O 17 B/O Source of Release Date and Hour of Occurrence Date and Hour of Discovery Production tank 8/11/2015; AM 8/11/2015; AM Was Immediate Notice Given? If YES, To Whom? ☐ Yes ☐ No ☒ Not Required N/A By Whom? Date and Hour N/A Was a Watercourse Reached? If YES, Volume Impacting the Watercourse.

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The dump failed, causing the production tank to overflow. Vacuum truck(s) and roustabout crews were called.

☐ Yes 🛛 No

Describe Area Affected and Cleanup Action Taken.\*

This release occurred on top of the 5/20/15 (2RP-3035) and 7/23/15 (2RP-3184) releases. A work plan was submitted for the two previous releases on 8/11/15 and approved by NMOCD on 8/14/15. This new release will be under the same work plan. Impacted soils (1.5' below surface level - as laid out in the work plan) were excavated on 8/15/15 and 8/19/15. The soils were hauled to a NMOCD approved facility. Further vertical delineation will be completed to ensure no further impact. If further sampling shows TPH/BTEX to be under the RRAL's a Final Report, C-141 will be submitted to the OCD requesting closure for this release. Depth to Ground Water: 50-99' (approximately 75', Section 16, T19S-R25E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Yates Petroleum requests closure based on all work being completed as per previously approved work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION Signature: Approved by Environmental Specialist: Printed Name: Amber Griffin Approval Date: 6/9/2016 Expiration Date: N/A Title: Environmental Representative Conditions of Approval: E-mail Address: agriffin@yatespetroleum.com Attached FINAL Date: June 7, 2016 Phone: 575-748-4111 2RP-3216

<sup>\*</sup> Attach Additional Sheets If Necessary