

Received 6/29/2016

NMOCD Artesia

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: XTO Energy	Contact: John Robinson
Address: P.O. Box 700 Eunice NM 88231	Telephone No. 575-441-5199
Facility Name: Goldenchild 006 State 1H; 2RP# 3677	Facility Type: Well
Surface Owner: State	Mineral Owner: API No. 30-015-43003

LOCATION OF RELEASE


Unit Letter P	Section 6	Township 25S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude: N 32.152575° Longitude: W 104.017629°

NATURE OF RELEASE

Type of Release: oil and produced water	Volume of Release: 10.10 oil and 90.90 produced water	Volume Recovered: 10 oil and 90 water
Source of Release: flow line	Date and Hour of Occurrence: 5/3/16 @ 8:00 am	Date and Hour of Discovery: 5/3/16 @ 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson. Voice message	
By Whom? John Robinson	Date and Hour: 5/3/16 @ 11:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* Flow line washed out and leaked 101 bbls of fluid on location. Pumper shut in well and called a vacuum truck to clean up all the fluid.		
Describe Area Affected and Cleanup Action Taken.* Leak stayed on well pad. We will clean up all contamination possible and replace with clean backfill. Samples were collected and sent to the lab for analysis. Based on laboratory analytical data the release area was excavated; contaminated soil was hauled to a state approved facility for disposal. With NMOCD approval the excavation was backfilled with clean soil.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist:	
Printed Name: John Robinson	Approval Date: 7/6/2016	Expiration Date: N/A
Title: Maintenance Foreman	Conditions of Approval:	
E-mail Address: john_robinson@xtoenergy.com	FINAL	Attached <input type="checkbox"/>
Date: 6-23-16 Phone: 575-441-5199		

* Attach Additional Sheets If Necessary

2RP-3677