

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 6/29/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Cedar Canyon 15 #1 SWD	Facility Type	SWD
Surface Owner	McDonald	Mineral Owner	
		API No.	30-015-42797

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
SW ¼	15	24S	29E					Eddy

Latitude N 32.21642° Longitude W 103.97952°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	155 bbls	Volume Recovered	154 bbls
Source of Release	Power outage caused skim tank spill	Date and Hour of Occurrence	06/17/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	06/20/2016 @ 1:17 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

A power outage caused a skim tank to spill 155 bbls of oil. A vacuum truck recovered 154 bbls of oil and the power was restored.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 60' x 120' on location inside the lined containment. Remediation was completed by vacuuming the residuals and power washing the inside of the containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				<u>OIL CONSERVATION DIVISION</u>	
Printed Name:	Casey Summers	Approved by Environmental Specialist:			
Title:	NM Environmental Advisor	Approval Date:	7/7/2016	Expiration Date:	N/A
E-mail Address:	Casey_Summers@oxy.com	Conditions of Approval:			Attached <input type="checkbox"/>
Date:	6-29-16	Phone:	(575) 513-8289	FINAL	

* Attach Additional Sheets If Necessary

2RP-3753