RE: BOPCO LP * PLU CVX JV BS #23H * 30-015-41392 * 2RP-3192

Bradley,

Your closure request is approved.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

Heather Patterson Environmental Specialist NMOCD District II Office (575)748-1283 ext.101 Cell (575)703-0228

From: Blevins, Bradley [mailto:BBlevins@BassPet.Com]
Sent: Tuesday, August 02, 2016 1:37 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Blevins, Bradley
Subject: Closeure Report PLU CVX JV BS 023H

Mike/ Heather

Please find the attached closure report for the PLU CVX JV BS 023H. If you have any questions please let me know. Thank you

Brad Blevins BOPCO, LP 522 W. Mermod, Suite 704 Carlsbad, NM 88220 Office-575-887-7329 Cell-1-432-214-3704 bblevins@basspet.com