

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 8/15/2016

NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas	
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905	
Facility Name: Bebop 36 WIMD State #2H	Facility Type: Producing Oil Well	
Surface Owner: State	Mineral Owner:	API No. 30-015-43320

#### LOCATION OF RELEASE

Unit Letter M	Section 36	Township 25S	Range 31E	Feet from the 185'	North/South Line South	Feet from the 450'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.07988951 Longitude -103.73832293

#### NATURE OF RELEASE

Type of Release: Oil/produced water	Volume of Release: approximately 10-15 bbls.	Volume Recovered: 10 bbls
Source of Release: Water tank	Date and Hour of Occurrence 6-18-16	Date and Hour of Discovery 6-18-16 10:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson	
By Whom? Zack Thomas	Date and Hour 6-18-16 12:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

Choke washed out on well head sending sand to separator causing dump to hang open. FWKO over pressured and in turn sent gas to production tanks causing damage to a water tank. A hole in the flowline also developed due to sand.

Describe Area Affected and Cleanup Action Taken.\*

Affected area- Well pad surface around well head. Pasture west of location was hit with light spray. Vacuum trucks were used to recover 5 bbls of produced water and 5 bbls oil. Final remediation was conducted in accordance with the NMOCD's Guidelines for Remediation of Spills, Leaks and Releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Zack Thomas	Approved by Environmental Specialist:		
Title: Environmental Rep.	Approval Date: 8/15/2016	Expiration Date: N/A	
E-mail Address: zthomas@mewbourne.com	Conditions of Approval:  FINAL		Attached <input type="checkbox"/>
Date: 8-15-16	Phone: 575-602-2188		

2RP-3754