

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Received 8/22/2016
State of New Mexico NMOCD Dist 2
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1619750175

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	HONEY GRAHAM STATE COM #004H	Facility Type:	Tank Battery

Surface Owner:	State	Mineral Owner:	API No.	30-015-41379
----------------	-------	----------------	---------	--------------

LOCATION OF RELEASE

Unit Letter B	Section 29	Township 26S	Range 28E	Feet from the 330'	North/South Line North	Feet from the 1980'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.019558 Longitude 104.1071777

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 5bbls of Produced Water	Volume Recovered: 4bbls of Produced Water
Source of Release: Heater Treater	Date and Hour of Occurrence: 7/11/2016 10:00:00 AM	Date and Hour of Discovery: 7/11/2016 10:00:00 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

A hole developed in the thermo coupler, the thermo coupler has been replaced with a new one.

Describe Area Affected and Cleanup Action Taken.*

The release was contained within a lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment has been cleaned and the facility is back into operation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 

Printed Name: Robert Grubbs Jr.

Title: Senior Environmental Coordinator

E-mail Address: rgrubbs@concho.com

Date: August 22, 2016 Phone: 432-683-7443

OIL CONSERVATION DIVISION

Approved by Environmental Specialist: MBratcher

Approval Date: 8/23/16

Expiration Date: N/A

Conditions of Approval: N/A

FINAL REPORT

Attached ☐

* Attach Additional Sheets If Necessary

2RP-3780