

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 6/28/2016  
NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: Woolley Tank Battery	Facility Type: Tank Battery	
Surface Owner: Federal	Mineral Owner:	API No. NA

#### LOCATION OF RELEASE

Unit Letter	Section 28	Township 17S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude 32.810986° Longitude -103.979151°

#### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 85 bbls PW	Volume Recovered: 75 bbls PW
Source of Release: Filter Pot	Date and Hour of Occurrence: 3/20/16 11:30 am	Date and Hour of Discovery: 3/20/16 11:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher – NMOCD / Jim Amos – BLM	
By Whom? Robert Grubbs Jr.	Date and Hour: 3/21/2016 12:38 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by a corroded nipple on a filter pot. All fluid was contained within the bermed area. A vacuum truck was dispatched to removal all standing fluids.

Describe Area Affected and Cleanup Action Taken.\*

The impacted area was to the south of the tanks inside the containment. This release was remediated under the guidance of the NMOCD and Bureau of Land Management.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo Davis	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 8/29/2016	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: June 27, 2016	Phone: 575-748-3940	FINAL

\* Attach Additional Sheets If Necessary.

2RP-3633