

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 8/31/2016  
NMOCD Dist 2

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nAB1605638032

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Government AB Federal #13	Facility Type	Well
Surface Owner	BLM	Mineral Owner	
		API No. 30-015-40920	

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	10	20S	28E					Eddy County, NM

Latitude N 32.58979° Longitude W 104.15874°

#### NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	0.5 bbl oil, 15 bbls produced water	Volume Recovered	2 bbls produced water, skim oil
Source of Release	Livestock opened valve at the well head	Date and Hour of Occurrence	02/11/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM			
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour 02/12/2016 @ 3:16 pm			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

Livestock opened a valve at the well head spilling 0.5 bbl oil and 15 bbls of produced water. A vacuum truck recovered 2 bbls of produced water and skim oil and the valve was closed.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 105' x 57' on location around the well head. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 03/16/2016 and approved by Henryetta Price of the BLM on 03/17/2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Casey Summers	Approved by Environmental Specialist:		MBratcher	
Title:	NM Environmental Advisor	Approval Date:	9/6/16	Expiration Date:	N/A
E-mail Address:	Casey_Summers@oxy.com	Conditions of Approval:		N/A	Attached <input type="checkbox"/>
Date:	8-31-16	Phone:		(575) 513-8289	

\* Attach Additional Sheets If Necessary

2RP-3562