

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 8/29/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report ☒ Final Report

Name of Company: Burnett Oil Co., Inc.	Contact: Johnny Titsworth	
Address: Burnett Plaza-Ste 1500, 801 Cherry St-Unit 9, Fort Worth, TX 76102	Telephone No. (432) 425-2891	
Facility Name: Stevens A	Facility Type: Tank Battery	
Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-38373

LOCATION OF RELEASE


Unit Letter M	Section 13	Township 17S	Range 30E	Feet from the 1219	North/South Line South	Feet from the 54	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	---------------------	------------------------	----------------

Latitude: 32.82253 Longitude: -103.93016

NATURE OF RELEASE

Type of Release: Oil/Water	Volume of Release: 3/437 bbls	Volume Recovered: 400 bbls water
Source of Release: power loss / tank overflow	Date and Hour of Occurrence: 2/3/16	Date and Hour of Discovery: 2/3/16
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM - S. Tucker & OCD - H. Patterson	
By Whom? Leslie Garvis	Date and Hour: 2/3/16 @ 12:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Loss of power at facility caused tanks to overflow		
Describe Area Affected and Cleanup Action Taken.* 60' x 80' area within the firewall. All standing fluid has been recovered. Area will be sampled and remediated.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Johnny Titsworth	Approved by Environmental Specialist: Accepted for Record 9/8/2016	
Title: HSE Coordinator	Approval Date: N/A	Expiration Date: N/A
E-mail Address: jtitsworth@burnettoil.com	Conditions of Approval:	
Date: Phone: (432) 425-2891	further remediation to be performed at site abandonment.	
		Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-3628