

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 9/7/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Long Draw 10 E Federal #1	Facility Type: Producing Oil Well

Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-36879
--------------------	--------------------	----------------------

LOCATION OF RELEASE

Unit Letter E	Section 10	Township 20S	Range 25E	Feet from the 2310'	North/South Line North	Feet from the 990'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude_32.588808_ Longitude_-104.478037__

NATURE OF RELEASE

Type of Release: Oil(9 bbls)	Volume of Release: 9 bbls	Volume Recovered:8 bbls
Source of Release: Oil Well	Date and Hour of Occurrence 5-13-14	Date and Hour of Discovery 5-13-14 9:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Ricky Apperson	Date and Hour 3-27-14 9:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


High flow rate of oil coming in and failure to close thief hatch on oil tank allowed oil to be released into secondary containment.

Describe Area Affected and Cleanup Action Taken.*

Affected area- Inside the containment.

Cleanup- Vacuum truck came and sucked up standing fluid from inside the containment (a total of 8 bbls were recovered and taken to Tweedy SWD), pressure washer cleaned of tanks and catwalk. Containment was lined with poly therefore no dig and haul was necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Zack Thomas		Approved by Environmental Specialist:	
Title: Environmental Rep.		Approval Date: 9/8/2016	Expiration Date: N/A
E-mail Address: zthomas@mewbourne.com		Conditions of Approval:	
Date: 6-2-14		FINAL	
Phone: 575-602-2188		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-2311