

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 9/7/2016

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Henry 8 IL Federal #1H	Facility Type: Producing Oil Well

Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-41781
--------------------	--------------------	----------------------

LOCATION OF RELEASE

Unit Letter I	Section 8	Township 20S	Range 29E	Feet from the 1750'	North/South Line South	Feet from the 150'	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.585521 Longitude -104.089160

NATURE OF RELEASE

Type of Release: Oil(5bbls)	Volume of Release: 5 bbls	Volume Recovered: 0 bbls
Source of Release: Separator	Date and Hour of Occurrence 7-8-14	Date and Hour of Discovery 7-8-14 5:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Duncan Whitlock	
By Whom? Zack Thomas	Date and Hour 7-9-14 7:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Site glass on separator failed when well pressured up causing oil mist to be sprayed out in the pasture to the Northeast. Separator was isolated to make repairs.

Describe Area Affected and Cleanup Action Taken.*

Affected area- Overspray out into the pasture 300 ft by 100 ft Northeast of the separation equipment. Two treatments of Micro Blaze were applied to vegetation in the affected area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Zack Thomas	Approved by Environmental Specialist:		
Title: Environmental Rep.	Approval Date: 9/8/2016	Expiration Date: N/A	
E-mail Address: zthomas@mewbourne.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 7-24-14	Phone: 575-602-2188		FINAL

* Attach Additional Sheets If Necessary

2RP-2382