

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

fAB1607040898

**Release Notification and Corrective Action**

nAB1607041077

**OPERATOR** Initial Report  Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland, TX 79701	Telephone No. 432-230-0077
Facility Name: GJ West Coop Unit North Tank Battery	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. N/A
----------------------	----------------	-------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	21	17S	29E					Eddy County, NM

Latitude N 32.82109° Longitude W 104.07641°

**NATURE OF RELEASE**

Type of Release: Oil and produced water	Volume of Release: 2 bbls oil, 3 bbls produced water	Volume Recovered: 2 bbls oil, 1 bbl produced water
Source of Release: Flowline	Date and Hour of Occurrence 02/24/2016 @ 12:00 pm	Date and Hour of Discovery 02/24/2016 @ 12:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

This release was caused by a corroded steel flow line. A vacuum truck was dispatched to recover standing fluid.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred along the west fence line of the battery. The site was delineated and a remediation plan was sent to NMOCD and the SLO. The remediation plan was approved by Mike Bratcher of NMOCD via email on 07/22/2016 and approved by Amber Groves of the SLO via email on 08/01/2016. Remediation was completed in accordance with the approved plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b><u>OIL CONSERVATION DIVISION</u></b>	
Printed Name: Robert Grubbs	Approved by Environmental Specialist: <i>MBratcher</i>	
Title: Senior Environmental Coordinator	Approval Date: 9/21/16	Expiration Date: N/A
E-mail Address: rgrubbs@concho.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: August 25, 2016	Phone: (432) 683-7443	FINAL

\* Attach Additional Sheets If Necessary

2RP-3607