

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 10/10/2016

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: WEST BRUSHY 8 FEDERAL SWD #001	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31675
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	08	26S	29E	660	North	330	East	Eddy

Latitude Longitude

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 30 bbls PW	Volume Recovered: 29 bbls PW
Source of Release: Water Tank	Date and Hour of Occurrence: 8/23/2016 at 8:30 PM	Date and Hour of Discovery: 8/23/2016 at 9:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher- NMOCD/ Shelly Tucker- BLM	
By Whom? Dakota Neel	Date and Hour: 8/25/2016 at 8:15 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a tank overflowing due to a header valve failing to close. The header valve was repaired.

Describe Area Affected and Cleanup Action Taken.*

This release was contained within a lined facility. Vacuum trucks were dispatched to pick up all standing fluids. The facility was pressure washed and the contaminated gravel was removed and replace with fresh gravel.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Dakota Neel		Approved by Environmental Specialist:	
Title: Environmental Coordinator	Approval Date: 10/13/2016	Expiration Date: N/A	
E-mail Address: dneel2@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: October 10, 2016	Phone: 575-748-6933	FINAL	

* Attach Additional Sheets If Necessary

2RP-3862