

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 10/7/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report


Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: CABO WABO 25 FEDERAL COM #003H	Facility Type: Battery	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42507

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	25	25S	29E	540	South	1650	East	Eddy

Latitude 32.0950394 Longitude -103.9346466

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 30 bbls	Volume Recovered: 27 bbls
Source of Release: Valve	Date and Hour of Occurrence: 9/1/2016 unknown	Date and Hour of Discovery: 9/1/2016 11:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Heather Patterson/NMOCD and Shelly Tucker/BLM	
By Whom? Dakota Neel	Date and Hour: 9/2/2016 9:53 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* This release was caused when a valve failed and remained in the wrong position. Vacuum trucks were dispatched immediately to recover all standing fluid.		
Describe Area Affected and Cleanup Action Taken.* The release remained within the lined containment. Vacuum trucks recovered all standing fluid. Contaminated gravel was removed and replaced with fresh gravel. The facility and equipment was pressure washed and cleaned.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Dakota Neel	Approved by Environmental Specialist:	
Title: Environmental Coordinator	Approval Date: 10/13/2016	Expiration Date: N/A
E-mail Address: dneel2@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: October 7, 2016 Phone: 575-748-6933		

* Attach Additional Sheets If Necessary

2RP-3891