

Received 10/10/2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NMOCD Dist 2

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1620449034

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: FIREFOX 4 FEDERAL COM #005H	Facility Type:

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-41423
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter M	Section 4	Township 19S	Range 31E	Feet from the 670	North/South Line South	Feet from the 250	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude Longitude

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 20 bbls Oil ; 5 bbls PW	Volume Recovered: 15 bbls Oil ; 3 bbls PW
Source of Release: Heater treater	Date and Hour of Occurrence: 7/11/2016 unknown	Date and Hour of Discovery: 7/11/2016 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher – NMOCD / Shelly Tucker – BLM	
By Whom? Amanda T. Davis	Date and Hour: 7/11/2016 6:21 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a hole in the heater treater. A vacuum truck was dispatched to recover free liquids and Microblaze was applied to the pasture areas.

Describe Area Affected and Cleanup Action Taken.*

This release occurred primarily in the containment however a spray of fluids impacted the nearby pasture. This release was remediated with an approved work plan under the guidance of NMOCD and BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Dakota Neel		Approved by Environmental Specialist: 	
Title: Environmental Coordinator	Approval Date: 10//17/16	Expiration Date: N/A	
E-mail Address: dneel2@concho.com	Conditions of Approval: N/A FINAL		Attached <input type="checkbox"/>
Date: October 10, 2016	Phone: 575-748-6933		

* Attach Additional Sheets If Necessary

2RP-3789