

From: [Patterson, Heather, EMNRD](#)
To: ["Blevins, Bradley"](#)
Subject: RE: PLU 347
Date: Thursday, October 20, 2016 6:46:00 AM

This one looks good to go, thank you Bradley.

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Blevins, Bradley [mailto:BBlevins@BassPet.Com]
Sent: Wednesday, October 19, 2016 11:02 AM
To: Patterson, Heather, EMNRD
Cc: Blevins, Bradley
Subject: PLU 347

Heather

Attached is the initial C-141 and lab data for the release that occurred on the PLU 347. As stated in the initial notification we were able to dispatch a backhoe to the location the same day that the release occurred to remove the saturated surface soils. In reviewing the attached lab report BOPCO would like to request no further action on this location, if approved we will backfill the surface scraped areas and submit a closure report. Thank you

Brad Blevins
BOPCO, LP
522 W. Mermod, Suite 704
Carlsbad, NM 88220
Office-575-887-7329
Cell-1-432-214-3704
bblevins@basspet.com