

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU #211; 2RP# 3705	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: API No. 30-015-33858

LOCATION OF RELEASE


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	18	24S	30E	1980	South	1980	East	Eddy

Latitude: N 32.215775° Longitude: W 103.918663°

NATURE OF RELEASE

Type of Release: produced water	Volume of Release: 14 bbls produced water	Volume Recovered: 5 bbl produced water
Source of Release: wellhead/polish rod pack off assembly	Date and Hour of Occurrence: 5/17/16 @ 2:30 pm	Date and Hour of Discovery: 5/17/16 @ 3:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* BOPCO EHS was notified of a release that occurred at the PLU 211 due to the polish rod pack off assembly was loose. The lease operator was able to tighten the pack off assembly and call for a vacuum truck to recover the standing fluid (5 barrels PW).		
Describe Area Affected and Cleanup Action Taken.* A vacuum truck was called to the location and was able to recover 5 barrels of produced water. Samples were collected and sent for testing. Based on laboratory analytical data and NMOCD approval the contaminated soil has been excavated and hauled to a state approved disposal facility, and the excavation backfilled with clean soil.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist:	
Printed Name: Bradley Blevins	Approval Date: 11/2/2016	Expiration Date: N/A
Title: Assistant Remediation Foreman	Conditions of Approval:	
E-mail Address: bblevins@basspet.com	FINAL	Attached <input type="checkbox"/>
Date: 10/19/2016 Phone: 432-214-3704		

* Attach Additional Sheets If Necessary

2RP-3705