

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 10/25/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland, TX 79701	Telephone No. 432-230-0077
Facility Name: Willow 17 State SWD #001	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. 30-015-41806
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	17	25S	28E	660	South	660	East	Eddy County, NM

Latitude N 32.12498° Longitude W 104.10342°

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 80 bbls	Volume Recovered: 0 bbls
Source of Release: Hose connecting to the load line	Date and Hour of Occurrence 07/24/2016 @ 8:00 am	Date and Hour of Discovery 07/24/2016 @ 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher- NMOCD	
By Whom? Robert Grubbs Jr.	Date and Hour: 07/25/2016 @ 9:28 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

A truck was unloading when his hose disconnected from the load line. Make sure the hose connect is secure before unloading.

Describe Area Affected and Cleanup Action Taken.*

This release occurred when the hose connection failed going to a load line on the pad. A 5 x 5 area went off in the pasture next to the location. The spill was delineated and a remediation plan was created. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 09/28/2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Robert Grubbs Jr		Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator		Approval Date: 11/2/2016	Expiration Date: N/A
E-mail Address: rgrubbs@concho.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: October 21, 2016 Phone: (432) 683-7443		FINAL	

* Attach Additional Sheets If Necessary

2RP-3812