

Received 11/8/2016

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NMOCD Dist 2

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

nAB1624352162

Release Notification and Corrective Action

nAB1624442573

OPERATOR
☐ Initial Report ☒ Final Report



Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	COPPERHEAD 30 FEE #001H	Facility Type:	Tank Battery
Surface Owner:	Private	Mineral Owner:	API No. 30-015-39542

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	30	26S	29E	480'	North	480'	East	Eddy

Latitude 32.0195389 Longitude 104.0167313

NATURE OF RELEASE

Type of Release:	Oil & Produced Water	Volume of Release:	5bbls of Oil & 30bbls of Produced Water	Volume Recovered:	4bbls of Oil & 26bbls of Produced Water
Source of Release:	FWKO	Date and Hour of Occurrence:	8/26/2016 1:30 pm	Date and Hour of Discovery:	8/26/2016 1:30 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mr. Bratcher – NMOCD / Ms. Groves - SLO			
By Whom?	Robert Grubbs Jr.	Date and Hour:	Mon 8/29/2016 12:32 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.* A gasket failed on a FWKO. Replaced the gasket with a high-pressure gasket.					
Describe Area Affected and Cleanup Action Taken.* This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. Concho had the free fluids and any contaminated material inside the lined facility removed. The liner has been cleaned and returned back to normal operations.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Robert Grubbs Jr.		Approved by Environmental Specialist: 			
Title: Senior HSE Coordinator		Approval Date: 11/17/16		Expiration Date: N/A	
E-mail Address: rgrubbs@concho.com		Conditions of Approval: N/A FINAL		Attached <input type="checkbox"/>	
Date: November 8, 2016 Phone: 432-683-7443					

* Attach Additional Sheets If Necessary

This release was opened twice
OCD error

2RP-3851
2RP-3854