

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 11/30/2016

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland, TX 79701	Telephone No. 432-685-4304
Facility Name: Tex-Mack #202	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner: State	API No. 30-015-35914
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	2	17S	31E	990	South	1650	West	Eddy County, NM

Latitude N 32.85893° Longitude W 103.84364°

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 10 bbls	Volume Recovered: 9 bbls
Source of Release: Produced water tank	Date and Hour of Occurrence 06/29/2016 @ 8:00 am	Date and Hour of Discovery 06/29/2016 @ 6:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Failure of a Murphy switch caused a leak of 10 bbls of produced water. A vacuum truck recovered 9 bbls of produced water and the Murphy switch was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area included an 80' x 6' area inside the firewall just north of the tanks. The site was sampled and a remediation plan was created. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 12/5/2016	Expiration Date: N/A
E-mail Address: rgrubbs@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: November 28, 2016 Phone: (432) 683-7443	FINAL	

* Attach Additional Sheets If Necessary

2RP-3768