

NMOC Dist 2

State of New Mexico NM
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

nAB1609935347

OPERATOR

☐ Initial Report x ☐ Final Report

Name of Company Matador Resources Company	Contact Catherine Green
Address 500 N Main St Ste 1 Roswell NM 88201	Telephone No. 575-623-6601
Facility Name Cedar 32 State Com #1	Facility Type Gas

Surface Owner New Mexico	Mineral Owner New Mexico	API No.30-015-27929
--------------------------	--------------------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	32	17S	31E	1980	N	660	E	Eddy

Latitude__32.7928734__ **Longitude**_-103.8853683_

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 12 BBLs	Volume Recovered 9BBLs
Source of Release Water not hauled by hauler, this tank overflowed.	Date and Hour of Occurrence Between April 4 and 5, 2016	Date and Hour of Discovery April 5, 2016 12noon
Was Immediate Notice Given? <div style="text-align: right;"> <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required </div>	If YES, To Whom? Catherine Green	
By Whom? Anthony Sanchez	Date and Hour April 5, 2016 12:00 noon	
Was a Watercourse Reached? <div style="text-align: right;"> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No </div>	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Lease operator telephoned water hauler to pick up a load of produced water. Water hauler neglected to collect the produce water. Produced water overflowed the tank. Standing water was vacuumed up and disposed of.

Describe Area Affected and Cleanup Action Taken.*

Stained soil around the produced water tank. Soil samples will be collected and analyzed. Any contaminated soil will be removed from around the produced water tank and disposed of. Fresh soil will be placed on location. Removed 6 feet of soil in delineation area and replaced.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: *Catherine S Green*

Printed Name: Catherine S. Green

Title: Regulatory Analyst

E-mail Address: cgreen@matadorresources.com

Date: Nov. 9, 2016 Phone: 575-623-6601

OIL CONSERVATION DIVISION

Approved by Environmental Specialist: WAB

Approval Date: 12/14/16

Expiration Date: N/A

Conditions of Approval: N/A

FINAL

Attached ☐

* Attach Additional Sheets If Necessary

2RP-3637