

Bratcher, Mike, EMNRD

From: Blaney, Karolina <Karolina.Blaney@wpxenergy.com>
Sent: Friday, December 16, 2016 2:26 PM
To: Patterson, Heather, EMNRD
Cc: Bratcher, Mike, EMNRD; stucker@blm.gov; Weaver, Crystal, EMNRD
Subject: RE: WPX RDU 61 - delineation workplan
Attachments: RDU 61 - delineation workplan.pdf

Please disregard the plan I sent previously; attached is the revised version.
Thank you Heather!!!

Karolina Blaney

Environmental Specialist

WPX Energy

Office: (575) 885-7514

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Blaney, Karolina
Sent: Friday, December 16, 2016 2:05 PM
To: 'Patterson, Heather, EMNRD' <Heather.Patterson@state.nm.us>
Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; stucker@blm.gov; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Subject: RE: WPX RDU 61 - delineation workplan

Good afternoon,
Attached is a delineation workplan for the spill that occurred at the RDU 61 well pad.
Please let me know if you have any questions or comments.
Thank you,

Karolina Blaney

Environmental Specialist

WPX Energy

Office: (575) 885-7514

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Patterson, Heather, EMNRD [<mailto:Heather.Patterson@state.nm.us>]
Sent: Thursday, November 17, 2016 10:55 AM
To: Blaney, Karolina <Karolina.Blaney@wpxenergy.com>
Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; stucker@blm.gov; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Subject: RE: WPX RDU 61 - initial C-141

Karolina,

Please see the attached Conditions of Approval for the Initial C-141 spill report you sent on 11/12/2016. Your tracking number for this event is 2RP-3989.

Heather Patterson
Environmental Specialist
NMOCD District II
Office (575)748-1283 ext.101
Cell (575)703-0228

From: Blaney, Karolina [<mailto:Karolina.Blaney@wpxenergy.com>]
Sent: Saturday, November 12, 2016 4:35 PM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; 'stucker@blm.gov'
Subject: RE: WPX RDU 61 - initial C-141

Good afternoon,
Attached is C-141 for the RDU 61 spill.
Please let me know if you have any questions or concerns.
Thank you,

Karolina Blaney
Environmental Specialist
WPX Energy
Office: (575) 885-7514
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com

From: Blaney, Karolina
Sent: Tuesday, November 01, 2016 2:19 PM
To: 'Patterson, Heather, EMNRD' <Heather.Patterson@state.nm.us>; 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>
Subject: WPX RDU 61 - spill notification

Good afternoon,

On 10/30/16, WPX had a small spill at the RDU 61 well pad, API # 30-015-41980. Approximately 15 bbls of water and oil were spilled on location due to mechanical failure; stainless steel line between the wellhead and Murphy's switch failed. We recovered 10 bbls of water and 3 bbls of oil. The impacted area was mapped, scraped off, and sampled. Further remediation will depend on the lab results. The C-141 report will be submitted within 15 days from the incident. Please let me know if you have any questions or concerns.
Thank you and have a great afternoon,

Karolina Blaney
Environmental Specialist
WPX Energy
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com