

## Bratcher, Mike, EMNRD

---

**From:** Bratcher, Mike, EMNRD  
**Sent:** Thursday, January 5, 2017 11:39 AM  
**To:** 'Blaney, Karolina'  
**Cc:** stucker@blm.gov; Weaver, Crystal, EMNRD  
**Subject:** RE: WPX RDU 61 - delineation workplan

RE: 2RP-3989

Karolina,

Your delineation proposal is approved. Target goal for chloride delineation is 250 mg/kg.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

Thank you,

Mike Bratcher  
NMOCD District 2  
811 S. First St.  
Artesia NM 88210  
575-748-1283 Ext 108  
mike.bratcher@state.nm.us

---

**From:** Blaney, Karolina [mailto:Karolina.Blaney@wpxenergy.com]  
**Sent:** Friday, December 16, 2016 2:26 PM  
**To:** Patterson, Heather, EMNRD <Heather.Patterson@state.nm.us>  
**Cc:** Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; stucker@blm.gov; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>  
**Subject:** RE: WPX RDU 61 - delineation workplan

Please disregard the plan I sent previously; attached is the revised version.  
Thank you Heather!!!

*Karolina Blaney*  
Environmental Specialist  
WPX Energy  
Office: (575) 885-7514  
Cell: (970) 589-0743  
[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)

---

**From:** Blaney, Karolina  
**Sent:** Friday, December 16, 2016 2:05 PM  
**To:** 'Patterson, Heather, EMNRD' <[Heather.Patterson@state.nm.us](mailto:Heather.Patterson@state.nm.us)>  
**Cc:** Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; [stucker@blm.gov](mailto:stucker@blm.gov); Weaver, Crystal, EMNRD <[Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us)>  
**Subject:** RE: WPX RDU 61 - delineation workplan

Good afternoon,  
Attached is a delineation workplan for the spill that occurred at the RDU 61 well pad.  
Please let me know if you have any questions or comments.  
Thank you,

*Karolina Blaney*  
Environmental Specialist  
WPX Energy  
Office: (575) 885-7514  
Cell: (970) 589-0743  
[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)

---

**From:** Patterson, Heather, EMNRD [<mailto:Heather.Patterson@state.nm.us>]  
**Sent:** Thursday, November 17, 2016 10:55 AM  
**To:** Blaney, Karolina <[Karolina.Blaney@wpxenergy.com](mailto:Karolina.Blaney@wpxenergy.com)>  
**Cc:** Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; [stucker@blm.gov](mailto:stucker@blm.gov); Weaver, Crystal, EMNRD <[Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us)>  
**Subject:** RE: WPX RDU 61 - initial C-141

Karolina,

Please see the attached Conditions of Approval for the Initial C-141 spill report you sent on 11/12/2016.  
Your tracking number for this event is 2RP-3989.

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

---

**From:** Blaney, Karolina [<mailto:Karolina.Blaney@wpxenergy.com>]  
**Sent:** Saturday, November 12, 2016 4:35 PM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; 'stucker@blm.gov'  
**Subject:** RE: WPX RDU 61 - initial C-141

Good afternoon,  
Attached is C-141 for the RDU 61 spill.  
Please let me know if you have any questions or concerns.  
Thank you,

*Karolina Blaney*  
Environmental Specialist  
WPX Energy

Office: (575) 885-7514  
Cell: (970) 589-0743  
[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)

---

**From:** Blaney, Karolina  
**Sent:** Tuesday, November 01, 2016 2:19 PM  
**To:** 'Patterson, Heather, EMNRD' <[Heather.Patterson@state.nm.us](mailto:Heather.Patterson@state.nm.us)>; 'Bratcher, Mike, EMNRD' <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; 'stucker@blm.gov' <[stucker@blm.gov](mailto:stucker@blm.gov)>  
**Subject:** WPX RDU 61 - spill notification

Good afternoon,

On 10/30/16, WPX had a small spill at the RDU 61 well pad, API # 30-015-41980. Approximately 15 bbls of water and oil were spilled on location due to mechanical failure; stainless steel line between the wellhead and Murphy's switch failed. We recovered 10 bbls of water and 3 bbls of oil. The impacted area was mapped, scraped off, and sampled. Further remediation will depend on the lab results. The C-141 report will be submitted within 15 days from the incident. Please let me know if you have any questions or concerns.  
Thank you and have a great afternoon,

*Karolina Blaney*  
Environmental Specialist  
WPX Energy  
Cell: (970) 589-0743  
[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)