

## Bratcher, Mike, EMNRD

---

**From:** Bratcher, Mike, EMNRD  
**Sent:** Thursday, January 5, 2017 11:48 AM  
**To:** 'Blaney, Karolina'; Weaver, Crystal, EMNRD  
**Cc:** Tucker, Shelly (stucker@blm.gov)  
**Subject:** RE: WPX RDU 11 - C-141

RE: 2RP-4001

Karolina,

Your proposal for delineation is approved. Target goal for chloride delineation is 250 mg/kg.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

Thank you,

Mike Bratcher  
NMOCD District 2  
811 S. First St.  
Artesia NM 88210  
575-748-1283 Ext 108  
mike.bratcher@state.nm.us

---

**From:** Blaney, Karolina [mailto:Karolina.Blaney@wpxenergy.com]  
**Sent:** Friday, December 23, 2016 11:58 AM  
**To:** Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>  
**Cc:** Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Tucker, Shelly (stucker@blm.gov) <stucker@blm.gov>  
**Subject:** RE: WPX RDU 11 - C-141

Good morning Crystal,  
Attached is the characterization plan for the RDU 11 spill.  
Please let me know if you have any questions or suggestions.  
Thank you and have a great Christmas!!!

*Karolina Blaney*  
Environmental Specialist  
WPX Energy  
Office: (575) 885-7514  
Cell: (970) 589-0743  
[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)

---

**From:** Patterson, Heather, EMNRD [<mailto:Heather.Patterson@state.nm.us>]  
**Sent:** Thursday, December 01, 2016 1:24 PM  
**To:** Blaney, Karolina <[Karolina.Blaney@wpxenergy.com](mailto:Karolina.Blaney@wpxenergy.com)>  
**Cc:** Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; Tucker, Shelly ([stucker@blm.gov](mailto:stucker@blm.gov)) <[stucker@blm.gov](mailto:stucker@blm.gov)>; Weaver, Crystal, EMNRD <[Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us)>  
**Subject:** RE: WPX RDU 11 - C-141

RE: WPX \* RDU #11 \* 30-015-24307 \* 2RP-4001

Karolina,

Attached are the Conditions of Approval for this C-141 Remediation Permit. The OCD tracking number for this event is 2RP-4001.

Thank you,

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

---

**From:** Blaney, Karolina [<mailto:Karolina.Blaney@wpxenergy.com>]  
**Sent:** Thursday, November 17, 2016 2:26 PM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; 'stucker@blm.gov'  
**Subject:** RE: WPX RDU 11 - C-141

Attached is C-141 for the RDU 11 spill.  
Thank you and have a great afternoon,

*Karolina Blaney*  
Environmental Specialist  
WPX Energy  
Office: (575) 885-7514  
Cell: (970) 589-0743  
[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)

---

**From:** Blaney, Karolina  
**Sent:** Sunday, November 06, 2016 11:09 AM  
**To:** 'Patterson, Heather, EMNRD' <[Heather.Patterson@state.nm.us](mailto:Heather.Patterson@state.nm.us)>; 'Bratcher, Mike, EMNRD' <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; 'stucker@blm.gov' <[stucker@blm.gov](mailto:stucker@blm.gov)>  
**Subject:** WPX RDU 11 - spill notification

Good morning,

Yesterday, 11/5/16, WPX had a spill at the RDU 11 well pad, API # 30-015-24307; T26S R30E S22. The cause of this spill is equipment failure. A pump air locked causing tank to overfill. 66 bbls of oil was recovered from a dirt SPCC containment berm; none of the fluids have left the containment. The C-141 report will be submitted within 15 days from the incident. Please let me know if you have any questions or concerns.

Thank you and have a great Sunday.

*Karolina Blaney*

Environmental Specialist

WPX Energy

Cell: (970) 589-0743

[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)