

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Artesia District II

Received  
12/22/16

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report



Name of Company: Mewbourne Oil Company	Contact: Zack Thomas	
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905	
Facility Name: Bradley 28 Fed Com #2H	Facility Type: Oil Well	
Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-39458

### LOCATION OF RELEASE

Unit Letter D	Section 28	Township 18S	Range 30E	Feet from the 500'	North/South Line North	Feet from the 150'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.7243652 Longitude -103.9850769

### NATURE OF RELEASE

Type of Release: Oil/Produced water	Volume of Release: 10 bbls	Volume Recovered:
Source of Release: Well head	Date and Hour of Occurrence 1-11-13	Date and Hour of Discovery 1-11-13
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*  Packing on the stuffing box wore out and oil/water started to leak of the stuffing box. Pumper replaced the packing on stuffing box.		
Describe Area Affected and Cleanup Action Taken.*  Area affected by the spill was just the location itself around the well head. Contaminated soil was removed to a depth of 1 foot and taken to R360. Sample results are attached.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Approved by Environmental Specialist: 	
Title: Environmental Rep.	Approval Date: 1/9/2017	Expiration Date: N/A
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 12-22-16	Phone: 575-602-2188	

\* Attach Additional Sheets If Necessary

2RP-1544