

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1636358002

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Lime Rock Resources II-A, L.P.	Contact: Mike Barrett
Address: 1111 Bagby St. Ste. 4600 Houston, TX 77002	Telephone No. 505-353-2644
Facility Name: Falcon 3 G Fed #7	Facility Type: Tank Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-29126
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter G	Section 3	Township 18S	Range 27E	Feet from the 1450	North/South Line N	Feet from the 2310	East/West Line E	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	-----------------------	-----------------------	---------------------	----------------

Latitude 32.779365 Longitude -104.265335

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 30bbls	Volume Recovered: 15bbls
Source of Release: Heater Treater	Date and Hour of Occurrence: 12/18/2016	Date and Hour of Discovery: 12/18/2016 9:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher-NMOCD Shelly Tucker-BLM	
By Whom? Sheldon Hitchcock-Talon/LPE	Date and Hour: 12/18/2016 at 1:20pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A midstream operator's line went down over night causing a backup in Lime Rock's system which resulted in a failure at the heater treater. The failure resulted in the loss of approximately 30bbls of crude oil. Upon discovery, crews were immediately dispatched to the site to begin recovering standing fluid utilizing a vacuum truck, scraping up saturated soil utilizing a backhoe, and collecting soil samples in preparation for a remediation work plan.

Describe Area Affected and Cleanup Action Taken.*

The fluid from the release impacted the northeast corner of the location and ran south off location and into the county road's ROW. The heavily impacted soil was scraped up and hauled to an NMOCD approved solid waste disposal facility. Signage was put in place to notify traffic of work on the shoulder and a permit to work inside of the county's ROW was obtained. Upon receipt of analytical data a remediation work plan was drafted and subsequently approved by NMOCD and BLM. The remediation proceeded in accordance with the approved work plan. The impacted soil was excavated and disposed of at a NMOCD approved solid waste disposal facility. The excavation was backfilled with caliche and contoured to match the surrounding location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Mike Barrett		Approved by Environmental Specialist: 	
Title: Production Supervisor		Approval Date: 1/18/17	Expiration Date: N/A
E-mail Address: mbarrett@limerockresources.com		Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 1/13/2017	Phone: 505-353-2644	FINAL	

* Attach Additional Sheets If Necessary

2RP-4048