

Bratcher, Mike, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Friday, January 20, 2017 1:56 PM
To: 'Kimberly M. Wilson'; Shelly Tucker
Cc: Weaver, Crystal, EMNRD; jctrucking@pvtm.net; David Adkins
Subject: RE: Myrtle Myra #8 * 30-015-21650 * 2RP-1572

RE: Endurance Resources * Myrtle Myra 8 * 2RP-1572 * DOR: 3/1/13

Kimberly,

Your request to commence liner installation and backfill operations is approved. Federal sites will require like approval from BLM.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

Mike Bratcher
NMOCD District 2
811 S. First St.
Artesia NM 88210
575-748-1283 Ext 108
mike.bratcher@state.nm.us

From: Kimberly M. Wilson [mailto:kwilson@talonlpe.com]
Sent: Friday, January 20, 2017 12:11 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Shelly Tucker <stucker@blm.gov>
Cc: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; jctrucking@pvtm.net; David Adkins <dadkins@talonlpe.com>
Subject: Myrtle Myra #8 * 30-015-21650 * 2RP-1572

Good morning Mike and Shelly,

Please find attached the confirmation samples for the sidewalls of the remediation activities carried out at the Myrtle Myra #8.

I was out on location while the remediation activities were in progress and performed field titration for chlorides on the sidewalls of the excavation. The excavation was guided by my field titration results and followed up by Laboratory results.

Attached is a table for the lab results to make it easier to read, along with the full laboratory results and site map. The sample locations are not on the site map yet but you can see how it flows around the edge of the impacted area.

Can we have permission to lay the liner and backfill the excavation? We would like to begin backfilling activities on Monday January 23, 2017.

If you have any questions or concerns please feel free to contact me.

Thank you.

Kimberly M. Wilson

Project Manager

408 West Texas Avenue

Artesia, New Mexico 88210

(575) 746.8768 office

(575) 616.4023 direct

(575) 602.3826 cell

(866) 742.0742 emergency

Email: kwilson@talonlpe.com

Web: www.talonlpe.com

