

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
**District II**  
811 S. First St., Artesia, NM 88210  
**District III**  
1000 Rio Brazos Road, Aztec, NM 87410  
**District IV**  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

nAB1623250530

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	PO Box 4294; Houston, TX 77210	Telephone No.	(575) 513-8289
Facility Name	Federal 12 #001 South CTB	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-26742

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	12	22S	31E					Eddy County, NM

Latitude N 32.40031° Longitude W 103.73792°

**NATURE OF RELEASE**



Type of Release	Oil and Produced water	Volume of Release	2 bbls oil, 12 bbls produced water	Volume Recovered	7 bbls
Source of Release	Pump failure caused the tank to spill over	Date and Hour of Occurrence	08/05/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy@BBC International, Inc.	Date and Hour	08/05/2016 @ 5:18 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Pump failure caused the tank to spill over and leak 2 bbls of oil and 12 bbls of produced water. A vacuum truck recovered 7 bbls of fluids and the pump was restored back to working condition.

Describe Area Affected and Cleanup Action Taken.\*  
The affected area is approximately 48' x 117' on location inside the berm of the battery. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 09/28/2016 and approved by Shelly Tucker of the BLM via email on 10/04/2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Casey Summers	Approved by Environmental Specialist:	
Title:	NM Environmental Advisor	Approval Date:	1/23/17
E-mail Address:	Casey_Summers@oxy.com	Expiration Date:	N/A
Date:	1-11-17	Conditions of Approval:	Like approval BLM <b>FINAL</b>
Phone:	(575) 513-8289	Attached	<input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2RP-3837