Bratcher, Mike, EMNRD

From: Tucker, Shelly <stucker@blm.gov>
Sent: Tuesday, January 31, 2017 2:21 PM

To: Laura Flores

Cc: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD; Michael Burton; Hickert, Aaron;

TButters@linnenergy.com

Subject: Re: Linn - Skelly A Battery (2R-3214) Closure Report

BLM will accept your closure for this release. Due to the volume released, I will not require labs to be submitted, but the area will be noted and my need to have further remedial activities at a later date if residual impact shows to be of an issue.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker
Environmental Protection

Environmental Protection Specialist O&G Spill/Release Coordinator

Bureau of Land Management 620 E. Greene St Carlsbad. NM 88220

575.234.5905 - Direct 575.361.0084 - Cellular

575.234.6235 - Emergency Spill Number

stucker@blm.gov

The <u>BLM acceptance/approval does not</u> relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Tue, Jan 31, 2017 at 1:49 PM, Laura Flores liflores@diversifiedfsi.com wrote:

Good afternoon.

Attached is the Closure Report for the Skelly A Battery (Skelly Unit #213) (2R-3214).
Please let us know if you have any questions.
Thank you,
Laura Flores
Report Writer
Environmental Department
Diversified Field Service, Inc.
206 W Snyder Hobbs, NM 88240
Phone: 575.964.8394 Fax: 575.964.8396