

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nAB1630555506



OPERATOR		Initial Report	X Final Report
Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	STATE GQ COM #003H	Facility Type:	Tank Battery
Surface Owner:	State	Mineral Owner:	API No. 30-015-40867

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	07	25S	28E	330'	North	380'	East	Eddy

Latitude 32.1509857 Longitude 104.1195908

### NATURE OF RELEASE

Type of Release:	Produced Water	Volume of Release:	37bbls	Volume Recovered:	35bbls
Source of Release:	4" Nipple	Date and Hour of Occurrence:	10-25-2016 3:00 pm	Date and Hour of Discovery:	10-25-2016 3:00 pm
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour:			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
This release was caused by a corroded 4" nipple connected to a load line. Replaced the corroded 4" nipple with a new coated 4" nipple.					
Describe Area Affected and Cleanup Action Taken.*					
Concho has had the free fluids and any impacted material inside the lined facility removed. The liner has been cleaned and the facility back in operation. This release occurred within a lined facility. A vacuum truck was dispatched to remove all freestanding fluids.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:					
Printed Name:	Robert Grubbs Jr.	Approved by Environmental Specialist: 			
Title:	Senior Environmental Coordinator	Approval Date:	2/22/17	Expiration Date:	N/A
E-mail Address:	rgrubbs@concho.com	Conditions of Approval: Containment Cleaned			
Date:	January 19, 2017	Liner inspected Attached <input type="checkbox"/>			
Phone:	432-683-7443				

\* Attach Additional Sheets If Necessary

2RP-3970