

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1631947928

OPERATOR

Initial Report X Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	Colt State #4 SWD	Facility Type:	Tank Battery



Surface Owner:	State	Mineral Owner:	API No. 30-015-41401
----------------	-------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 05	Township 25S	Range 28E	Feet from the 1066	North/South Line North	Feet from the 850	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude Longitude

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 75 bbls	Volume Recovered: 74 bbls
Source of Release: Tank Battery	Date and Hour of Occurrence: 11/7/2016 3:45 pm	Date and Hour of Discovery: 11/7/2016 3:45 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Two-Inch nipple on the bottom of the filter pot broke. Repaired the filter pot.		
Describe Area Affected and Cleanup Action Taken.* This release occurred within a lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho has had the free fluids and any impacted material inside the lined facility removed. The liner has been cleaned and the facility back in operation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist: 	
Title: Senior HSE Coordinator	Approval Date: 2/22/17	Expiration Date: N/A
E-mail Address: rgrubbs@concho.com	Conditions of Approval: Containment Cleaned Liner inspected	Attached <input type="checkbox"/>
Date: January 19, 2017	Phone: 432-683-7443	

* Attach Additional Sheets If Necessary

2RP-3988