

Received 1/25/2017
NMOCD Dist 2

District 1
1625 N. French Dr. Hobbs, NM 88240
District 2
1111 N. First St. Artesia, NM 88210
District 3
1000 Red Blazes Road, Aztec, NM 87410
District 4
1220 S. St. Francis Dr. Santa Fe, NM 87505

2RP-1486
State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 18, 2011
Submit 1 copy to appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nJMW1300851642

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: EOG Resources, Inc.	Contact: Zane Kurtz
Address: 5509 Champions Dr., Midland, TX 79705	Telephone No.: 432-425-2023
Facility Name: Ross Gulch 8 Fed Com #211	Facility Type: Tank Battery
Surface Owner: BLM	Mineral Owner: BLM
API No.: 30-015-39171-00-X1	

LOCATION OF RELEASE

Unit Letter: N	Section: 8	Township: 26S	Range: 31E	Feet from the: 330	North/South Line: South	Feet from the: 1540	East/West Line: West	County: Eddy
----------------	------------	---------------	------------	--------------------	-------------------------	---------------------	----------------------	--------------

Latitude 32.0636885° Longitude -103.8035110°

NATURE OF RELEASE



Type of Release: Crude Oil	Volume of Release: 10 bbl	Volume Recovered: 0 bbl
Source of Release: Malfunction of dump valve at separator	Date and Hour of Occurrence: 12-05-2012, 3:00PM	Date and Hour of Discovery: 12-06-2012, 10:30AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Geoffrey Leking (OCD District 1)	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse:	

If a Watercourse was Impacted, Describe Fully *

Describe Cause of Problem and Remedial Action Taken. *Initial C-141 states - lost pressure to separator dump and liquid went through the flare, spraying the pasture west of location. Dump valve will be adjusted.

Describe Area Affected and Cleanup Action Taken. * Initial C-141 states - oil sprayed an area in pasture approx. 100 yards x 150 yards. Spot mopped the most impacted area with absorbent pads. Bio-remediated in place the entire affected area with approx. 1,500 gallons of 4% Microblaze/Water mixture. This method was approved by BLM and soil samples will be taken to ensure proper levels of TPH are reached. On October 4, 2016, SDR personnel applied Gator8 bioremediation amendment to the spill and tilled the soil. On December 30, 2016 and January 17, 2017, LAI personnel collected confirmation samples (SS-1 through SS-10) which were analyzed for TPH (GRO, DRO and ORO) and BTEX. The laboratory reported BTEX and TPH below the RRAL. EOG requests no further action for 2RP-1486. The remediation area will be seeded with BLM seed blend No. 2.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Zane Kurtz, EOG Resources, Inc.	Approved by Environmental Specialist: 	
Title: Sr. Environmental Representative	Approval Date: 3/2/17	Expiration Date: N/A
E-mail Address: zane_kurtz@eogresources.com	Conditions of Approval: Like approval from BLM	Attached <input type="checkbox"/>
Date: 01-20-2017	Phone: 432-556-8074	

* Attach Additional Sheets If Necessary

2RP-1486

2RP-1486