From: <u>Patterson, Heather, EMNRD</u>

To: "Zane Kurtz"; Lynch, Kristen, EMNRD

Cc: <u>Bratcher, Mike, EMNRD; Crystal EMNRD Weaver (Crystal.Weaver@state.nm.us)</u>

Subject: RE: Ross Gulch 8-3 SWD C-141

Date: Thursday, November 17, 2016 10:46:00 AM

Attachments: coa 3993.pdf

Zane,

Please see the attached Conditions of Approval for the Initial C-141 spill report you sent on 11/14/2016. Your tracking number for this event is 2RP-3993.

Heather Patterson Environmental Specialist NMOCD District II Office (575)748-1283 ext.101 Cell (575)703-0228

From: Zane Kurtz [mailto:Zane_Kurtz@eogresources.com]

Sent: Monday, November 14, 2016 9:23 AM

To: Lynch, Kristen, EMNRD

Cc: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD

Subject: RE: Ross Gulch 8-3 SWD C-141

Will do. Thanks

From: Lynch, Kristen, EMNRD [mailto:Kristen.Lynch@state.nm.us]

Sent: Monday, November 14, 2016 9:13 AM **To:** Zane Kurtz < <u>Zane Kurtz@eogresources.com</u>>

Cc: Patterson, Heather, EMNRD < Heather.Patterson@state.nm.us>; Bratcher, Mike, EMNRD

<mike.bratcher@state.nm.us>

Subject: FW: Ross Gulch 8-3 SWD C-141

** External email. Use caution.**
Good Morning,

This is a District 2 site. Please follow up with them regarding this site.

Thank You,

Kristen D. Lynch Environmental Specialist, District 1 Oil Conservation Division, EMNRD (575) 393-3896 ext. 111 575-370-3180 (emergency-cell)

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Zane Kurtz [mailto:Zane_Kurtz@eogresources.com]

Sent: Friday, November 11, 2016 6:10 AM

To: Lynch, Kristen, EMNRD **Cc:** Jamon Hohensee

Subject: FW: Ross Gulch 8-3 SWD C-141

Good Morning

Sorry I wasn't able to send the C-141 yesterday. I had Jamon prepare it. When I was out there they were crushing the tanks to haul off. We only lost 3 fiberglass tanks. It was a 4 tank battery. A part of the containment was crushed and some fluids got out onto the pad. Nothing went off pad. We are going to rebuild the battery but on the other side of the pad. Once all equipment is moved we will have a consultant go out and assess the area for any impacts.

From: Jamon Hohensee

Sent: Thursday, November 10, 2016 2:15 PM

To: Kristen.Lynch@state.nm.us

Cc: Zane Kurtz < <u>Zane Kurtz@eogresources.com</u>>

Subject: Ross Gulch 8-3 SWD C-141

Kristen, here is the C-141 for the lightning strike at the Ross Gulch 8-3 SWD on 11-6-16.

Jamon Hohensee

Environmental Rep EOG Resources, Inc. Mobile 432-556-8074