

Received 3/8/2017

NMOCD Dist 2

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

## Oil Conservation Division

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.**Release Notification and Corrective Action**

nJMW1302234481



**OPERATOR**☐ Initial Report ☒ Final Report

Name of Company	Chevron USA	Contact	Josepha DeLeon
Address	6301 Deauville Blvd, Midland, TX 79706	Telephone No.	(575) 263-0424
Facility Name	Lentini 1 Federal Battery	Facility Type	Tank Battery
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-27535

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	1	23S	28E					Eddy County, NM

Latitude N 32.33723°Longitude W 104.04356°**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	46.295 bbls	Volume Recovered	30 bbls
Source of Release	Flow line	Date and Hour of Occurrence	12/01/2012	Date and Hour of Discovery	12/01/2012 @ 8:50 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD			
By Whom?	Amy Barnhill	Date and Hour 12/02/2012 @ 11:00 am			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A pin hole in the body of a flowline caused a leak of approximately 46 bbls of produced water. The valve was switched to stop flow. A vacuum truck was dispatched to recover 30 bbls of produced water.					
Describe Area Affected and Cleanup Action Taken.*					
The area affected is approximately 103' x 30' at the southwest corner of the location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 09/02/2016 and approved by Shelly Tucker of the BLM via email on 08/26/2016.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		<b>OIL CONSERVATION DIVISION</b>			
Printed Name: Josepha DeLeon		Approved by Environmental Specialist: 			
Title: HES Compliance Support- Environmental		Approval Date: 3/9/17		Expiration Date: N/A	
E-mail Address: jdx@chevron.com		Conditions of Approval: Like approval from BLM		Attached <input type="checkbox"/>	
Date: 3/7/17		Phone: (575) 263-0424			

\* Attach Additional Sheets If Necessary

2RP-1510