

Bratcher, Mike, EMNRD

From: Tucker, Shelly <stucker@blm.gov>
Sent: Monday, January 9, 2017 10:01 AM
To: Bratcher, Mike, EMNRD
Cc: Michael Alves; Laura Flores; Michael Burton; john_robinson@xtoenergy.com; Weaver, Crystal, EMNRD
Subject: Re: XTO - Nash Unit #042 H Work Plan

BLM concurs with the NMOCD.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist
O&G Spill/Release Coordinator

Bureau of Land Management
620 E. Greene St
Carlsbad, NM 88220

575.234.5905 - Direct
575.361.0084 - Cellular
575.234.6235 - Emergency Spill Number

stucker@blm.gov

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Thu, Jan 5, 2017 at 2:19 PM, Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us> wrote:

Michael,

Thank you for the data. We are 1' closer to our goal, which is a **complete delineation**. Delineation means to show where contaminants clean up, or how far they have gone vertical and horizontal. When I said 1' increments, I should have added "until site is delineated". I just assumed that was a given. OCD will not consider a proposal until the site has been delineated to show where contaminants clean up to RRAL, or for chloride, 250 mg/kg, or to the maximum extent practicable. If you have questions about this concept, please contact me or schedule a meeting. I am amenable to either.

Thanks,

Mike Bratcher

NMOCD District 2

811 South First Street

Artesia NM 88210

575-748-1283 Ext 108

mike.bratcher@state.nm.us

From: Michael Alves [mailto:malves@diversifiedfsi.com]

Sent: Thursday, January 5, 2017 12:07 PM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Laura Flores <lflores@diversifiedfsi.com>; Tucker, Shelly <stucker@blm.gov>

Cc: Michael Burton <mburton@diversifiedfsi.com>; john_robinson@xtoenergy.com; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>

Subject: RE: XTO - Nash Unit #042 H Work Plan

Here is the results at 1' for all 4 sample points.

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]

Sent: Wednesday, January 04, 2017 2:31 PM

To: Laura Flores <lflores@diversifiedfsi.com>; Tucker, Shelly <stucker@blm.gov>

Cc: Michael Alves <malves@diversifiedfsi.com>; Michael Burton <mburton@diversifiedfsi.com>;

john_robinson@xtoenergy.com; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>

Subject: RE: XTO - Nash Unit #042 H Work Plan

RE: XTO Energy * Nash 42 CTB * **2RP-3976** * DOR: 10/17/16

Greetings,

Your proposal for remediation of the above referenced release is **not** approved. OCD concurs with BLM assessment that the site lacks adequate lab data to consider this proposal. OCD requests impacted gravel in the battery be removed, the liner inspected for holes, tears, etc., and clean gravel replaced. In the event the liner has been compromised, OCD is to be notified. If the liner is intact, photos are encouraged for documentation. Impacted areas outside the lined battery area will require at a minimum, lab data from samples obtained at 1' increments. A remedial proposal may then be considered based on actual data.

If you have any questions or concerns, please contact me.

Mike Bratcher

NMOCD District 2

811 South First Street

Artesia NM 88210

575-748-1283 Ext 108

mike.bratcher@state.nm.us

From: Laura Flores [<mailto:lflores@diversifiedfsi.com>]

Sent: Tuesday, December 6, 2016 10:41 AM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Tucker, Shelly <stucker@blm.gov>

Cc: Michael Alves <malves@diversifiedfsi.com>; Michael Burton <mburton@diversifiedfsi.com>;

john_robinson@xtoenergy.com

Subject: XTO - Nash Unit #042 H Work Plan

Good morning.

Attached is the Work Plan for the XTO Nash Unit #042H site.

Please let me know if you have any questions or comments.

Thank you,

Laura Flores

Report Writer

Environmental Department

Diversified Field Service, Inc.

206 W Snyder | Hobbs, NM 88240

Phone: 575.964.8394 | Fax: 575.964.8396