

From: [Weaver, Crystal, EMNRD](#)
To: ["Chase Settle"; "Zane_Kurtz@eogresources.com"; Bratcher, Mike, EMNRD; Billings, Bradford, EMNRD](#)
Cc: ["Bob Asher"; "Amber Griffin"; "Veronica Alvarado"](#)
Subject: RE: Compromise SWD #1 C-141
Date: Thursday, May 18, 2017 1:07:00 PM
Attachments: [image001.png](#)

Hello all,

I stand corrected. There were additional documents beyond the memo I cited as the last document OCD had received. They were just not in the places I was looking. So for that mix up I apologize.

Ok, so monitoring wells were installed and water samples were taken from the 3 wells back in July 2015. However, an update on this site would still be ideal since the consultant did recommend quarterly water samples be taken.

Thank you,

Crystal Weaver

Environmental Specialist

OCD – Artesia District II

811 S. 1st Street

Artesia, NM 88210

Office: 575-748-1283 ext. 101

Cell: 575-840-5963

Fax: 575-748-9720

From: Weaver, Crystal, EMNRD
Sent: Thursday, May 18, 2017 12:41 PM
To: 'Chase Settle' <Chase_Settle@eogresources.com>; 'Zane_Kurtz@eogresources.com' <Zane_Kurtz@eogresources.com>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Billings, Bradford, EMNRD <Bradford.Billings@state.nm.us>
Cc: Bob Asher <Bob_Asher@eogresources.com>; Amber Griffin <Amber_Griffin@eogresources.com>; Veronica Alvarado <Veronica_Alvarado@eogresources.com>
Subject: RE: Compromise SWD #1 C-141

RE: EOG Y * Compromise SWD #1 * 30-015-25665 * 2RP-4208 and follow up request on 2RP-2797

Chase,

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an

attached Conditions of Approval. The OCD tracking number for this event is 2RP-4208.

PLEASE NOTE: OCD has reviewed this API location and noted that there have been 7 documented spills that have involved either the battery site or the SWD well. OCD would like to, at this point, pose the question, to EOG Y Resources, of is there any intention to replace infrastructure for Compromise SWD # 1 and the tank batteries?

Also during my investigation of this file, I came across **2RP-2797** which had a DOR of 1/16/15 with 2500bbls of produced water from a hole in a surface supply line. After vigorous efforts by OCD members it was finally agreed upon that monitoring wells would be installed and it was claimed that a permit was applied for from OSE for said wells. The last document we have is a memo from Safety & Environmental Solutions proposing procedures for monitoring well installation. I have attached that document and the original C-141 above. Please expedite your efforts to provide an update on this matter as soon as possible.

Thank you,

Crystal Weaver

Environmental Specialist

OCD – Artesia District II

811 S. 1st Street

Artesia, NM 88210

Office: 575-748-1283 ext. 101

Cell: 575-840-5963

Fax: 575-748-9720

From: Chase Settle [mailto:Chase_Settle@eogresources.com]

Sent: Monday, May 15, 2017 3:24 PM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>

Cc: Bob Asher <Bob_Asher@eogresources.com>; Amber Griffin <Amber_Griffin@eogresources.com>; Veronica Alvarado <Veronica_Alvarado@eogresources.com>

Subject: Compromise SWD #1 C-141

Please find attached the C-141 Initial for the below listed location. This release site has already undergone initial sampling on May 8, 2017. Background sampling will be conducted the week of May 22-26, 2017, the exact time and date has not been determined and will be dependent upon contractor availability.

Compromise SWD #1

30-015-25665
1980 FNL & 800 FEL (UL-H)
Section 30, T18S-R27E
Eddy County, New Mexico

Thank you,

Chase Settle, M.S.
Rep Safety & Environmental II

EOG Resources

105 S. 4th Street
Artesia, NM 88210
575-748-4171 (Office)
575-703-6537 (Cell)

