

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1629542376

OPERATOR

Initial Report Final Report

Name of Company	OXY USA INC	Contact	CASEY L SUMMERS
Address	PO BOX 4294; HOUSTON, TX 77210	Telephone No.	575-513-8289
Facility Name	FNR 26 FEDERAL #1 CTB	Facility Type	BATTERY

Surface Owner	BLM	Mineral Owner	BLM	API No.	30-015-30412
---------------	-----	---------------	-----	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	26	23S	30E	660	SOUTH	660	WEST	EDDY

Latitude_ N 32.26969°_ Longitude_ W 103.85422°_ NAD83

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	10 bbls	Volume Recovered	0 bbls
Source of Release	Compromised 3" poly water transfer line	Date and Hour of Occurrence	10-3-2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson-NMOCD, Shelly Tucker-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	10/03/2016 @ 4:34PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

A compromised 3" poly water transfer line spilled 10 bbls of produced water off location. No fluids were recovered and the line was repaired.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 25' x 25' approximately 700 feet east of location. Remediation was completed in accordance with the remediation plan approved for the release (2RP-3946) by Shelly Tucker of the BLM on 11/21/2016 and Mike Bratcher of the NMOCD on 11/29/2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: CASEY L SUMMERS	Approved by Environmental Specialist: 		
Title: ENVIRONMENTAL ADVISOR	Approval Date: 6/15/17	Expiration Date: N/A	
E-mail Address: casey_summers@oxy.com	Conditions of Approval: N/A		Attached <input type="checkbox"/>
Date: 5-31-17 Phone: 575-513-8289	FINAL		

* Attach Additional Sheets If Necessary

2RP-3946