

Received 6/29/2017

NMOCD Dist 2

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nABI700440434

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	OXY USA INC	Contact	CASEY L SUMMERS
Address	PO BOX 4294; HOUSTON, TX 77210	Telephone No.	575-513-8289
Facility Name	SUNDANCE 8 FEDERAL #1 CTB	Facility Type	BATTERY
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-27228

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	8	24S	31E	330	NORTH	1650	WEST	EDDY

Latitude 32.2382126 Longitude -103.8030472 NAD83

NATURE OF RELEASE

Type of Release	OIL	Volume of Release	13 bbls	Volume Recovered	3 bbls
Source of Release	Bleeder valve on the circulating pump was left open	Date and Hour of Occurrence	12/11/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	MIKE BRATCHER-NMOCD; HEATHER PATTERSON-NMOCD; SHELLEY TUCKER - BLM		
By Whom?	KATHY PURVIS @ BBC INTERNATIONAL INC	Date and Hour	12/13/2016 @ 11:17 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The bleeder valve on the circulating pump was left open spilling 13 bbls of oil on location. A vacuum truck recovered 3 bbls of oil and the valve was closed.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 250' x 40' on location. Remediation was completed in accordance with the remediation plan approved for the release (2RP-4054) by Shelly Tucker of the BLM on 2-14-2017 and Mike Bratcher of the NMOCD on 2/15/2017.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health of the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: CASEY L SUMMERS		Approved by Environmental Specialist: 	
Title: ENVIRONMENTAL ADVISOR		Approval Date: 7/11/2017	Expiration Date: N/A
E-mail Address: casey_summers@oxy.com		Conditions of Approval: Like approval BLM	
Date: 5-17-17 Phone: 575-513-8289		FINAL Attached <input type="checkbox"/>	

* See closure report

2RP-4054