

-015-26407
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural Resources
 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-141
 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company Devon Energy Production Company	Contact Wesley Ryan, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-390-5436
Facility Name Laguna Salado South 1	Facility Type Gas

Surface Owner State	Mineral Owner State	API No 30-015-26407
----------------------------	----------------------------	----------------------------

LOCATION OF RELEASE

Unit Letter F	Section 22	Township 23S	Range 29E	Feet from the 2030	North/South Line North	Feet from the 1980	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.2922554

Longitude: -103.9748001

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 21bbbs	Volume Recovered 10bbbs
Source of Release Transfer line	Date and Hour of Occurrence January 26, 2017 @ 6:00PM	Date and Hour of Discovery January 26, 2017 @ 6:00PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker, BLM Mike Bratcher, OCD	
By Whom? Wesley Ryan, Production Foreman	Date and Hour Shelly Tucker, BLM January 27, 2017 @ 1:14 PM Mike Bratcher, OCD January 27, 2017 @ 9:25 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Water transfer line between the Laguna Salado South 1 and the Remuda Basin SWD 1 was struck by a rancher's backhoe. The transfer pumps were immediately shut down and the pipeline was isolated on both ends.

Describe Area Affected and Cleanup Action Taken.*
Approximately 21bbbs produced water was released due to the line strike. The release traveled in a West direction along the lease road in approximately a 4' to 24' wide by 1135' long area, it also traveled down a sandy two track road in a Southwest direction in an approximately a 12' wide by 107' long area. A vacuum truck was called and recovered approximately 10bbbs. Environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date:	Expiration Date:
E-mail Address: Sheila.fisher@dvn.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 1/31/17 Phone: 575.748.1829		

* Attach Additional Sheets If Necessary