

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nAB1701351977

OPERATOR☐ Initial Report ☒ Final Report

Name of Company COG Operating LLC	Contact Robert McNeil
Address 600 West Illinois Ave., Midland TX 79701	Telephone No. (432) 683-7443
Facility Name Puckett 13 Federal Tank Battery	Facility Type Tank Battery

Surface Owner: Federal	Mineral Owner	API No. 30-015-40737
------------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 12	Township 17S	Range 31E	Feet from the 43	North/South Line South	Feet from the 590	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	---------------------	---------------------------	----------------------	------------------------	----------------

Latitude N 32.8420105° Longitude W 103.81648258°

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release 2 bbls oil & 3 bbls water	Volume Recovered 1 bbls oil & 2 bbls water
Source of Release: Portable Tester	Date and Hour of Occurrence 01/06/17 7:00 pm	Date and Hour of Discovery 01/06/17 7:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour .	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

N/A


Describe Cause of Problem and Remedial Action Taken.*

The release occurred due to a pop off valve on a portable tester, which has been taken out of service. The release occurred on the pad area. A vacuum truck was dispatched to remove all standing fluids.

Describe Area Affected and Cleanup Action Taken.*

Tetra Tech inspected site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

		<u>OIL CONSERVATION DIVISION</u>	
Signature:		Approved by District Supervisor: 	
Printed Name: Ike Tavarez			
Title: Project Manager		Approval Date: 10/13/17	Expiration Date: N/A
E-mail Address: Ike.Tavarez@TetraTech.com		Conditions of Approval: Like Approval BLM	
Date: 07/17/17 Phone: (432) 682-4559		Attached <input type="checkbox"/>	
		FINAL	

* Attach Additional Sheets If Necessary

2RP-4073