

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nAB1702443626

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Remnant Oil Operating, LLC	Contact Carie Stoker
Address PO BOX 5375, Midland, TX 79704	Telephone No. 432 664 7659
Facility Name Chama 3 Federal #1H	Facility Type Battery

Surface Owner BLM	Mineral Owner BLM	API No. 31-015-36007
-------------------	-------------------	----------------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	03	18S	23E	1880	S	660	E	EDDY

Latitude 32.7749977 Longitude -104.6727142 NAD83

#### NATURE OF RELEASE

Type of Release Produced Water	Volume of Release EST 100 bbls	Volume Recovered 130 bbls *(see note)
Source of Release Water Tank	Date and Hour of Occurrence 1/15/17	Date and Hour of Discovery 01/15/17
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Email sent to Mike Bratcher and Jim Amos	
By Whom? Carie Stoker	Date and Hour 1/15/17 5:49 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*



Cause of problem: Lightning strike

Remedial Action Taken: Vacuum truck dispatched to recover standing fluids: \* an additional 30 bbls of fluid was recovered-this was due to the water being used by the firetrucks to put out the fire it was also raining during the incident

Describe Area Affected and Cleanup Action Taken.\*

Location has been remediated to NMOCD standards and all excavated soils have been transported to an NMOCD approved disposal facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Carie Stoker	Approved by Environmental Specialist: 	
Title: Regulatory Affairs Coordinator	Approval Date: 10/13/17	Expiration Date: N/A
E-mail Address: carie@stokeroilfield.com	Conditions of Approval: Like Approval BLM	
Date: 9/8/17 Phone: 432 664 7659	FINAL	Attached <input type="checkbox"/>