

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1702737974

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Wade Dittrich
Address	PO Box 4294; Houston, TX 77210	Telephone No.	(575) 390-2828
Facility Name	Spuds 25 Federal Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	API No. 30-015-29882

LOCATION OF RELEASE



Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	25	24S	29E					Eddy County, NM

Latitude N 32.18353° Longitude W 103.94360°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20 bbls	Volume Recovered	15 bbls
Source of Release	3 rd Party trucking company struck a tank causing it to spill	Date and Hour of Occurrence	01/10/2017	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Crystal Weaver- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy Purvis @ BBC International	Date and Hour	01/12/2017 @ 11:36 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A third party trucking company struck a tank causing it to spill 20 bbls of produced water. A vacuum truck recovered 15 bbls of produced water.					
Describe Area Affected and Cleanup Action Taken.*					
The affected area is approximately 75' x 150' on location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 04/03/2017 and approved by Shelly Tucker of the BLM via email on 04/18/2017.					

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Wade Dittrich	Approved by Environmental Specialist: 		
Title: Environmental Coordinator	Approval Date: 10/13/17	Expiration Date: N/A	
E-mail Address: Wade.Dittrich@oxy.com	Conditions of Approval: Like Approval BLM		Attached <input type="checkbox"/>
Date: 8-23-17	Phone: (575) 390-2828	FINAL	

* Attach Additional Sheets If Necessary

2RP-4091