

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 10/13/2017
NMOCD Dist 2

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1725440089

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Myox 5 State Com #022H	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner: State	API No. 30-015-43706
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	05	26S	28E	225	South	2,280	East	Eddy

Latitude 32.06501508 Longitude -104.1082911

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 25 bbl.	Volume Recovered: 24.75 bbl.
Source of Release: Water Transfer Pump	Date and Hour of Occurrence: September 5, 2017 2:00 pm	Date and Hour of Discovery: September 5, 2017 2:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Weaver - NMOCD / Ms. Groves - SLO	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The release was due to corrosion of a 2 by 1 steel swedge on a water transfer pump. The swedge was replaced.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment was pressure washed to remove any residue from the release. The lined containment was inspected and found to be structurally sound.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Aaron Lieb	Approved by Environmental Specialist: 		
Title: Senior HSE Coordinator	Approval Date: 10/24/17	Expiration Date: N/A	
E-mail Address: alieb@concho.com	Conditions of Approval: N/A		Attached <input type="checkbox"/>
Date: Phone: 432-683-7443	FINAL		

* Attach Additional Sheets If Necessary

2RP-4378