

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 10/20/2017

NMOCD Dist 2

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nAB1709342160

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Fasken Oil and Ranch	Contact: Aaron Pachlhofer, P.G.
Address: 6101 Holiday Hill RD, Midland, TX 79707	Telephone No.: 432-687-1777
Facility Name: El Paso Federal No. 12	Facility Type Tank Battery

Surface Owner: Federal	Mineral Owner: Federal	API No.: 30-015-30634
------------------------	------------------------	-----------------------

### LOCATION OF RELEASE

Unit Letter O	Section 1	Township 21-S	Range 26-E	Feet from the 4379	North/South Line North	Feet from the 1780	East/West Line East	County Eddy
------------------	--------------	------------------	---------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

### NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 31	Volume Recovered: 0
Source of Release: Oil Tank, release by theft	Date and Hour of Occurrence 3/25/17	Date and Hour of Discovery 3/25/17 9:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD Artesia District Supervisor	
By Whom? Aaron Pachlhofer	Date and Hour: 3/27/17 3:37 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

Unknown amount of oil spilled during theft of oil. 31 barrels is missing according to Fasken data. Area affected does not indicate that 31 barrels was released.

Describe Area Affected and Cleanup Action Taken.\*

Affected area confined primarily to inside of battery firewall. Small area on top of battery firewall and onto drive area of battery pad. No free oil remaining upon discovery. Clean up of contaminated soils expected 3/30/17.  
All visibly affected soils removed. Confirmation samples collected with concentrations lower than OCD limits. Excavation back filled with new, clean material. Excavated soil and gravel stockpiled on plastic for bio remediation. Stockpile sampled on 8/28/17 with concentrations lower than OCD limits. Spill response complete.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Aaron Pachlhofer, P.G.		Approved by Environmental Specialist: 	
Title: Environmental Coordinator		Approval Date: 10/27/17	Expiration Date: N/A
E-mail Address: aaronp@forl.com		Like Approval BLM	
Date: 10/18/17 Phone: 432-687-1777		Conditions of Approval: FINAL	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2RP-4155